INFORMATION REPORT INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

COUNTRY	Rumania	REPORT
UBJECT	Port of Constanta	DATE DISTR. 9 September 1955
ATE OF INFO.		NO. OF PAGES 3
		REQUIREMENT
ACE ACQUIRED		REFERENCES
ATE ACQUIRED		This is UNEVALUATED Information
	SOURCE EVALUATIONS ARE DEFINITIVE	. APPRAISAL OF CONTENT IS TENTATIVE.

Nautical Data

1. The appraoch to the harbor at Constanta conforms exactly to NEMEDRI and is not difficult to navigate. Harbor depths are all according to the Admiralty Chart. On the attached sketch, Point 1 is a shallow or shoal; Point 2 plots the course of entry into the harbor; Point 3 indicates where the ship anchored and turned; and, Point 4 shows the mooring position.

Shipping Wharves

25X1

Petroleum Harbors

- 3. In the old petroleum harbor, at Point 13, five ships can be loaded at the same time; two on the short branch and three on the long branch. In the old harbor there are five 10-inch petroleum pipe conduits above ground at a height of about five feet (sic). The conduits run completely through to
- h. In the new petroleum harbor, three ships can be loaded at the same time. The petroleum conduits, a total of six conduits of 10 inches each, are underground here and come up at the construction jetties. In the new harbor, as well as the old, are construction jetties. These jetties are located at Point 14, but are not marked on the Admiralty chart. The load capacity is about 200 tons. Loading and bunkering of fuel oil and diesel


· · ·	D-E-C-R-E-T	•	
			25X1
STATE X ARMY X NAVY	EV X AIR X FBI	AEC	
	(Note: Washington d	istribution indicated by "X"; Field distribution by "#".)	
,		**************************************	

INFORMATION REPORT INFORMATION REPOR

	S-E-C-R-E-	<u>r </u>	
			25 - 1
	- 2 -		
			25
oil is not possible b for harbor workers ar	ecause the same pipes are located at Point 21.	are used for this. Canto	ens
Harbor Installations			
At the new pier, Point cranes of ten tons. I floating crane with a there are three cranes	Canacity of short lo	e. At Point 16, there i	o s a nt 17
Ships			
Ships were berthed at	the following points:		
	n passenger ship, TRAN	SYLVANIA.	
b. Point 19 - various	ships.		25
c. Point 20 - four tu	gs (two steam and two makers and one naval tug	notor tugboats), two smal	25
Miscellaneous			•
A hud?dd== == = = = = = = = = = = = = = = =	egiska i karantari karantari da 1890. Tarantari karantari	ed the harbor master, th	
			25
	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		
	S-E-C-R-E-T	<u></u>	·
			25
	* *		

S-E-C-R-E-T 25X1
- 3 - 25X1

PORT OF CONSTANTA



25X1